

# State of Utah DEPARTMENT OF NATURAL RESOURCES Division of Oil, Gas & Mining

MICHAEL R. STYLER Executive Director JOHN R. BAZA Division Director

## Inspection Report Minerals Regulatory Program June 23, 2010

August 31, 2016

4	Pres
Reviewed:	10

Mine Name: Topaz Mine	Permit Number: M/023/0003			
Operator Name: Brush Resources, Inc.	Inspection Date: August 31, 2010			
Inspector(s): Wayne Western, Ivan Djambov legislature auditor, Jill Marriott accounting department	Time: 11:15 AM – 12:30 PM			
Other Participants: John Wagoner, Permittee	Mine Status: Active			
Elements of Inspection	Evaluated	Comment	Enforcement	
1. Permits, Revisions, Transfer, Bonds		$\boxtimes$		

	Elements of Inspection	Evaluated	Comment	Enforcement
1.	Permits, Revisions, Transfer, Bonds			
2.	Public Safety (shafts, adits, trash, signs, highwalls)	$\overline{\boxtimes}$		
3.	Protection of Drainages / Erosion Control	$\overline{\boxtimes}$	$\square$	
4.	Deleterious Material			
5.	Roads (maintenance, surfacing, dust control, safety)			
6.	Concurrent Reclamation	$\overline{\boxtimes}$		
7.	Backfilling/Grading (trenches, pits, roads, highwalls, shafts, drill holes)			
8.	Water Impoundments			
9.	Soils			
10.	Re-vegetation			
11.	Air Quality			
12.	Other			

#### **Purpose of Inspection:**

The purpose of this inspection was to conduct a tour of the facility for the legislature auditor and DNR accountant to familiarize them with mining operations.

### **Inspection Summary:**

- 1. The Permittee is current on permit fees. The bond amount is for \$1,362,000 and will be renewed on December 29, 2011.
- 2. The Permittee posts signs warning the public about mining operations.
- 3. Drains appeared to be functioning, no signs of erosion.
- 5. Road surfaces were maintained and no dust was observed.
- 6. The Operator reseeded the Fluro area in December 2009. Some new plants were noted during the inspection. Photographs of the area were taken.
- 12. The Operator wants to modify the NOI and asked for meeting the Division's staff in August.

Inspection Date: August 31, 2010

Page 2 of 3 M/023/0003

The Permittee conduct a tour of the site. The group observed the operational pit, the areas of reclamation and areas where expansion will most likely occur.

#### **Conclusions and Recommendations:**

The Division should continue to monitor the site.


Inspector's Signature Wayne Wayne Wales

CC: (OPERATOR)


cc: (OPERATOR)

SITLA

O:\M023-Juab\M0230003-Topaz-brush\inspections\Insp\_06222010.doc



Operational Pit



Operational Pit